

MARKETING BULLETIN Roofing Systems

717 17th St. Denver, CO 80202 (800) 922-5922

Bulletin Number: M22-008

Date: May 17, 2022 **Distribution:** External

Temporary Changes to JM Fastener Packaging

As part of the ongoing efforts to reliably supply JM materials to our customers through this period of supply chain challenges and elevated demand, JM is temporarily utilizing non-traditional cardboard boxes in lieu of plastic containers for some fastener products due to supply constraints associated with the standard plastic pails.

The below photo indicates the alternate carboard box packaging on the left and the traditional plastic container packaging on the right.



This temporary package solution may be utilized for the following JM materials:

High Load Phillips 2" 1000/Box	70000189
High Load Phillips 3" 1000/Box	70000190
High Load Phillips 4" 1000/Box	70000113
UltraFast Phillips 2-1/4" 1000/Bx	70000148
UltraFast Phillips 3" 1000/Bx	70002653
UltraFast Phillips 4" 1000/Bx	70002660
UltraFast Phillips 5" 1000/Bx	70000153

AP Phillips 1.25" 1000/Box	70000749
AP Phillips 1.75" 1000/Box	70000747
AP Phillips 2" 1000/Box	70000106
AP Phillips 3" 1000/Box	70000107
AP Phillips 4" 1000/Box	70000108
AP Phillips 5" 500/Box	70000109
AP Phillips 6" 500/Box	70000110

Please rely on label information and not package/container type when receiving into inventory or utilizing on a job. The piece counts per box and per pallet, for these various materials, are identical between the two packaging types.

Thank you for your continued business and support of JM products. Please contact your JM Representative with any questions.

Matt Sayer Senior Product Manager